

Lathe Cutting Tools

Lathe Cutting Tool Holder



80° Lathe Cutting Tool



35° Lathe Cutting Tool




45° Lathe Chamfering Tool



60° V Threading Tool



Grooving Tool .125



Grooving Tool .072



Parting Tool .200 Insert



Parting Tool .125 Insert



Boring Bar



Knurling Tool



Brazed Lathe Cutting Tool



**Drill Cuck Mounted to Lathe
Morse Taper 4 Arbor**



**Hole Chamfering, Small
Lathe Morse Taper 4 Arbor**



**Hole Chamfering
Lathe Morse Taper 4 Arbor**



Live Center, Lathe



Center Drill, Lathe



Drill Bit in a Lathe Chuck



Chuck Key for Drill Chuck



Drill Bit in a Tapered Shank



1 3/8" End Mill in a Morse Taper Arbor



7/16" End Mill in a Morse Taper Arbor



**Drill Bit Size Template Guides
Fractional, Numbers 1 through 80 and
Letters A through Z**



I-Tech 344 Manual Air Compressor Parts:

Piston, Connecting Rod, Dowel Pin, Brass Bushings, Set Screw, and Cap Bolt



First Stage Crankshaft Fixture



Second Stage Crankshaft Fixture

